

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002845**Date Inspected:** 09-Jun-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1830**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

CWI Name:	N/A		
Inspected CWI report:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A

CWI Present:	Yes	No
Rod Oven in Use:	Yes	No
Weld Procedures Followed:	Yes	No
Verified Joint Fit-up:	Yes	No
Approved WPS:	Yes	No
Delayed / Cancelled:	Yes	No
Component:	Deck panel/skin plates	

Bridge No: 34-0006**Summary of Items Observed:**

Per ZPMC UT inspection notification (00504, 00500 & 00503) this inspector performed Ultrasonic Testing (UT) verification of the QC UT Inspected and accepted welds. QA Inspector's visual and UT verification appears to be acceptable with AWS D1.5-02 section 6, table 6.3. Reference QA Ultrasonic Test Report TL-6027 dated 6/09/08 for specific test data.



Item	Description
1	Picture upper left

WBS

Dwg No.

Status

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

ESDI SA77D/E Skin Plate welds UT 10%

2 Picture upper right

10% UT of CJP diaphragm plate welds DP581-001

Summary of Conversations:

None noted

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Kelsey,David
----------------------	--------------

Quality Assurance Inspector

Reviewed By:	Cochran,Jim
---------------------	-------------

QA Reviewer
